Navajo Abandoned Uranium Mine Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits and pits. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites lands not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands but that are or may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, to record all immediate site information associated with the mine site and to document the recommendation and/or decision on what additional steps, if any, are needed at the site.

Crownpoint, Section 9 AUM Site

Navajo AUM Eastern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

May 2009

Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable Mine ID: 315 Map ID: E11 **CERCLIS:** NNN 000 908 705 **NAMLRP:** NOT ASSIGNED New Mexico Mining and Mineral Division ID: NM0144 New Mexico Bureau of Geology and Mineral Resources: NNMK0038 Local name / Aliases: Crownpoint, Section 9, Mobil Chapter and local area: Crownpoint Chapter **Lat/Long:** 35.7169371348 N / -108.230977229 W **Nearby road and highway:** NM-371, Interstate 40 Local Post Office: Crownpoint, NM Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Tribal Fee Land** Allotment Fee land **Public lands Private Bureau of Land Mgmt** State

Ownership and contact information:

No ownership was identified. The mine site property is classified as Indian Allotment land. A trailer is currently located in the eastern portion of the site, although it appears to be uninhabited (Photo 1). The majority of the site, with exception of the western extension, is fenced in, and was inaccessible during the site visit.

Part II Site Observations

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: A trailer home in located in the eastern section of the site, it appeared to be uninhabited. A horse stable was also observed near the trailer (Photo 1, 2)

200 feet to 0.25 mile: A house was located 200 feet north of the western portion of the site (Photo 4). Gamma radiation levels collected near the house we below 2 times background levels. A horse stable was also observed approximately 200 feet east of the site (Photo 3). No residents were encountered at either feature.

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None 200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

- House north of site – measured at less than 2 times background levels

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None 0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents.

Note information on mine ownership, period of operation, and type of mining operation.

Crownpoint, Section 9 mine consists of an area of 77,628.93 square meters. Any historical information pertaining to mining operations and historical ownership of the mine site appeared to be unclear.

Part III Type, number and reclamation status of mine features

Provide description and reclamation status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all reclamation caps.

Reclamation status of the mine site is currently unknown.

Part IV Summary of radiological readings

Background Locations

#1 12,808 counts per minute (cpm) #2 10,156 cpm

Mine site: Crownpoint, Section 9 - See Figures 1 and 2

Nearby Structure Perimeter – N/A

Describe any other radiological measurements:

A total of 1,717 gamma radiation measurements were collected from mine sites, ranging from 8,951 cpm to 15,386 cpm. The measurements are represented in Figures 1 and 2.

Part V Site sketch of all mine features and readings, including locations of all structures, sources of drinking water and any other important features and radiological readings.

Presented in Figures 1 and 2

Part VI Response Action Summary

Site Name(s): Crownpoint, Section 9 **Chapter:** Crownpoint

Decision Criteria

Is there an unreclaimed waste pile at the site? No

At what distance from the waste pile is the nearest residential structure located? N/A

At what distances from the waste pile are there potential drinking water sources? N/A

Is there a reclamation cap or sealed adit in place at the site? No

Is the cap/seal functionally intact? N/A

Is the cap/seal sufficiently degraded to create a concern about releases? N/A

At what distance from the cap/seal is the nearest domestic structure located? N/A

At what distance from the cap/seal is the nearest domestic drinking water source? N/A

Summary of emergency response factors

None

Summary hazard ranking system factors

A trailer home and horse stable were observed within the eastern portion of the site, which appeared to be uninhabited. A house was observed approximately 200 feet north of the site, and a horse stable was observed approximately 200 east of the site, gamma radiation levels at both were less than 2 times background levels.

Summary of reclamation factors

No known reclamation

Part VII Photos



Photo 1. Crownpoint Section 9, trailer within fenced-in area, towards the west



Photo 2. Crownpoint Section 9, stables within fenced-in area, towards the west



Photo 3. Wooden shed and stables directly east of site perimeter fence, towards the east



Photo 4. House approximately 200 feet north of mine site, towards the north

Part VIII Contacts Reports and Information

Name_Stanley Edison
Title or official role (if any) Navajo EPA Superfund Program
Address PO Box 2946, Window Rock, AZ 86515
Telephone number(928) 871-6861
Information provided <u>General Background and Contact/Access Information</u>
Name_Ms George Padilla
Title or official role (if any) Regional Environmental Scientist, BIA, Navajo Nation
Telephone number(505) 863-8434
Address PO Box 1060, Gallup, NM 87305
Name
Title or official role (if any)
Telephone number
Information provided
Name
Title or official role (if any)
Telephone number
Information provided



